



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

May 14, 2013

Reviewed: 

<b>Mine Name:</b> Ekins East	<b>Permit Number:</b> M/049/0032
<b>Operator Name:</b> Staker Parsons Company	<b>Inspection Date:</b> May 14, 2013
<b>Inspector(s):</b> Lynn Kunzler & April Abate	<b>Time:</b> 2:00 PM
<b>Other Participants:</b> Tom Nicolaysen (intern)	<b>Mine Status:</b> Reclamation

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Permit Fees:** Not received for 2013

**Bond: Surety \$29,000\***

#### Purpose of Inspection:

The purpose of the inspection is to introduce new lead, April Abate to the site. Examined the site to see what remaining reclamation work needs to be completed.


#### Inspection Summary:

No activity was observed on the site. The access gate was open. A small structure was on the site. According to Lynn, this structure will remain as part of the post-mining land use. The remaining reclamation work to be completed is focused on the flat (parking lot) area on the site.

#### Conclusions and Recommendations:

\*There is a discrepancy in the remaining bond amount. Foxpro and the bond calc file show \$29K. However, inspection notes show that operator believes amount is 13K. *The bond was verified in the Division files to be a surety bond in the amount of \$29,000. This was a replacement surety bond from 2006.* Should discuss with operator and also discuss remaining reclamation activities to be completed at the site.

**Inspector's Signature**



cc: Staker Parsons Company

O:\M049-Utah\M0490032-EkinsEast\inspections\Insp\_051413.doc